

Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 1. Overview of location taken facing east.



Photo 2. Example of equipment stored on location.



Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 3. Ongoing vapor release with stained gravel below ball valve.



Photo 4. Opposite angle but still upwind of ongoing release from ball valve.



Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 5. Crude tanks appear to have overflowed.



Photo 6. Crude tanks appear to have overflowed.



Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 7. Free fluid and saturated soil in tank battery berm.



Photo 8. Free fluid and saturated soil in tank battery berm.



Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 9. Free fluid and saturated soil in tank battery berm.



Photo 10. Free fluid and saturated soil in tank battery berm.



Inspection Photos
Location Name: Smith 1
Location ID: 313052



Photo 11. Free fluid and saturated soil in tank battery berm.



Photo 12. Example of equipment stored on location.

