

Inspection Photos
Location Name: Spike State CC 6-11J
API ID: 123-07639



Photo #1 Well, Sign, Weeds & Tore down fence. On 10/31/19



Photo #2 Well, Sign, Weeds & Tore down fence. On 11/14/19

