

Inspection Photos
Location Name: Spike State CC 6-14
API ID: 123-16203



Photo #1 Well, Sign, & Weeds. On 10/22/19



Photo #2 Well, Sign, & Weeds. On 11/14/19

Inspection Photos
Location Name: Spike State CC 6-14
API ID: 123-16203



Photo #3 Variance tag & Weeds. On 10/22/19



Photo #4 Variance tag & Weeds. On 11/14/19