

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 1 Dead weeds on access road

Photo 2 Dead weeds throughout location

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 3 WH sign displaying old operator information

Photo 4 WH

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 5 Heated Horiz. Sep.

Photo 6 TB sign

Inspection Photos
Location Name: Shoe #1
Location ID: 317489



Photo 7 Gas meter Run.