

Inspection Photos
Location Name: PATTI C 31-33
API#: 05-071-08950
INSP. #: 695101717



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: PATTI C 31-33
API#: 05-071-08950
INSP. #: 695101717



PHOTO 3: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE OIL STAINED. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-14-19



PHOTO 4: TWO UNUSED RISERS NEAR METER HOUSE. REMOVE UNUSED RISERS IN ACCORDANCE WITH RULE 603.f. AND NTO. CA DATE 2-14-20.