

Inspection Photos
Location Name: LADYHAWKE 41-31 TR
API#: 05-071-09118
INSP. #: 695101731



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos

Location Name: LADYHAWKE 41-31 TR

API#: 05-071-09118

INSP. #: 695101731



PHOTO 3: FUEL GAS SEPARATOR IS BEING DRAINED ON LOCATION CAUSING OIL CONTAMINATION ON LOCATION. IMMEDIATELY STOP DRAINING FUEL GAS SEPARATOR IN LOCATION, Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-14-19.



PHOTO 4: AREA OF IMPACTED SOIL NEAR COMPRESSOR. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-14-19.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources