

**KP Kauffman - COGCC Inspection Photos**  
**Location: Facility #8 Consolidation line Release**  
**Spill ID #469095**



**Overview of area where spill occurred. View North.**



**Spill response work in progress; impacted soils being removed.**

**KP Kauffman - COGCC Inspection Photos**  
**Location: Facility #8 Consolidation line Release**  
**Spill ID #469095**



**Surface expression of area where pipeline failed resulting in spill.**



**Bell hole excavation at release point; looking south toward second bellhole.**

**KP Kauffman - COGCC Inspection Photos**  
**Location: Facility #8 Consolidation line Release**  
**Spill ID #469095**



**Close up view of 10" Facility #8 consolidation pipeline cut for repairs; exposed in south bellhole.**



**Excavation work at south bellhole**