

Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 1. Location.

Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 2. Tank battery.

Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 3. Well head.

Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 4. Separators.

Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 5. Emission control devices.



Wiley 23-3-97 H1
API: 05-103-11954
Inspection: 679706117



Photo 6. Tank with incomplete label.



Photo 7. Stack with bird protection.