

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

688306286

**FIELD INSPECTION FORM**

Loc ID 429843 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 202 TRAVIS STREET #402

City: HOUSTON State: TX Zip: 77002

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
McCann, Randall	337-654-9804	rmccann@pcminc.com	Designated Agent
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429842	WELL	SI	06/01/2019	OW	073-06477	JOHN CRAIG 6-2	SI

**General Comment:**

Routine Inspection

Form 10 is in process, sending inspection to both operators until approved.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:		Date:	
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment: gas		Date:	
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment: pilots on		Date:	
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 4		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	200 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment: in berms with 3 treaters					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	<50 BBLs	STEEL AST		,
Comment: scrubber tank					
Corrective Action:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: in berms with crude oil tanks and produced water tanks						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	400 BBLS	STEEL AST		,	
Comment: Produced water tanks are full and have rust on some of the bottoms and one is rusted on the side (see attached photos). Inspect, maintain and repair tanks following standard industry practice such as API 12R.						
Corrective Action: Inspect, maintain and repair tanks following standard industry practice such as API 12R.						Date: 12/13/2019

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: same metal berms as crude oil tanks						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	400 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent				
Comment:						
Corrective Action:						Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 429842 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** Form: (04 )  
400692465  
01/22/2015 1) The flaring of natural gas shall be conducted in accordance with COGCC Rule 912 for the initial production test period. 2) Notify the local emergency dispatch or the local governmental designee of any natural gas flaring. 3) If flaring will continue more than 6 months, submit updated requests to flare to COGCC on Form 4 (Sundry Notice), which discusses timing to connect to sales line, plans to develop infrastructure, and justification for continued venting/flaring. 4) The operator is required to obtain and maintain any required air permits from CDPHE. 5) The venting or flaring volumes shall be reported by Form 7, Operator's Monthly Report of Operations. Well is shut in/TA and approved by Form 4.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:****Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Corrective Action:** \_\_\_\_\_ Date: \_\_\_\_\_**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

**Inspected Facilities**Facility ID: 429842 Type: WELL API Number: 073-06477 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [SI Marmaton since May 2015. Cherokee TA. Approved MIT 4/27/2018. Document 400752236 04 -00 -TA-SPUD-OTHER APPROVED 12/15/2014.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402237195	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986281">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986281</a>
688306314	D90 Energy/KTM John Craig 6-2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986273">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986273</a>