

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402242866

Date Received:

11/19/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>
<u>Ray, Mandi</u>	<u>505-324-5122</u>	<u>mray@hilcorp.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Roland, Kandis</u>		<u>kroland@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 687905748

Inspection Date: 11/04/2019

FIR Submit Date: 11/04/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 443138

Location Name: Anderson Number: 2-5H & 3-5H County: LA PLATA  
Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N  
Latitude: 37.039400 Longitude: -107.515400

FACILITY - API Number: 05-067- -00 Facility ID: 443139

Facility Name: ANDERSON Number: 3-5H  
Qtrqtr: SESE Sec: 5 Twp: 32N Range: 6W Meridian: N  
Latitude: 37.039400 Longitude: -107.515400

CORRECTIVE ACTIONS:

1 CA# 133186

Corrective Action:

Date: 11/30/2016

Erosion and bare soils need to be stabilized immediately. Reclaimed soils will need erosion controls during site stabilization. All stormwater and erosion controls need to be selected, installed, and maintained in accordance with good engineering practices such as those described by CDOT in their erosion control manuals. Corrective action is back-dated to document time out of compliance.

Response: CA COMPLETED

Date of Completion: 11/19/2019

Operator Comment: Crews installed rock check dams along the access road, backfilled erosion areas, and seeded bare areas, Crews also diverted the drainage from the location entrance off the pad to mitigate further erosion.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mandi Walker

Signed: \_\_\_\_\_

Title: Operation/Regulatory Tech

Date: 11/19/2019 9:49:58 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402242877	rock check dam
402242878	rock check dam 2
402242879	rock check dam 3
402242880	rock check dam 4
402242882	drainage
402242883	backfill
402242885	well sign

Total Attach: 7 Files