

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Colorado Oil & Gas Conservation Commission
40.37217, -104.43765, 1362.0m, 194°
11/19/2019 04:28:19 PM

Photo #1
DOW 32-28 (05-123-20656) Wellsite
Plugged & Abandoned | PA
~ 20 yds.
Appears to be cut & capped
Reclamation progressing



Colorado Oil & Gas Conservation Commission
40.37523, -104.43843, 1369.0m, 145°
11/19/2019 04:35:28 PM

Photo #2
DOW 32-28 Battery site
Abandoned | Most equipment removed
Reclamation progressing
Unused Gas meter runs

Inspection Photos
Location Name: DOW-65N63W /28SWNE
Location #: 331413



Photo #3
DOW 32-28 Wellsite
Plugged & Abandoned | PA
Unused equipment
Deadman anchors – 4 on site



Photo #4
DOW 32-28 Wellsite
Plugged & Abandoned | PA
Junk
Cut casing pipe, well fence