


Inspection Photos  
Operator Name: Caerus  
Location ID: 335023



**Wells shut in and Locked out and tagged out**

**Inspection Photos**  
**Operator Name: Caerus**  
**Location ID: 335023**



**Hydrovac truck on location digging down to flowline.**  
**LT Environmental on site**