

Inspection Photos
Location Name: YVONNE 41-14 FOLLOW UP
API#: 05-071-06445
INSP. #: 695101786



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: YVONNE 41-14
API#: 05-071-06445
INSP. #: 695101788



PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION (2" EXHAUST PIPE AND A 2" BLACK POLY PIPE). REMOVE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE 12-20-19.