

**Inspection Photos**  
**Location Name: MOLTRER 31-7**  
**API #: 05-071-06522**  
**Insp. Doc. # 695100146**



**PHOTO 1: WELLHEAD**



**PHOTO 2: WELL SIGN NOT POSTED/METER HOUSE**



**Inspection Photos**  
**Location Name: MOLTRER 31-7**  
**API #: 05-071-06522**  
**Insp. Doc. # 695100146**



**PHOTO 3: EROSION ON DITCH CROSSING TO THE SOUTH/EAST OF LOCATION**




**PHOTO 4: EROSION ON DITCH CROSSING TO THE SOUTH/EAST OF LOCATION**

**Inspection Photos**  
**Location Name: MOLTRER 31-7**  
**API #: 05-071-06522**  
**Insp. Doc. # 695100146**



Colorado Oil & Gas Conservation Commission  
37.10471, -104.70813, 2022.0m, 33°  
2019/02/08 15:03:30

**PHOTO 5: EROSION ON DITCH CROSSING TO THE SOUTH/EAST OF LOCATION**



Colorado Oil & Gas Conservation Commission  
37.10479, -104.70924, 2022.0m, 88°  
2019/02/08 15:05:30

**PHOTO 6: CA FOR GAS METER CALIBRATION HAS BEEN COMPLETED**