

## Inspection Photos

Location Name: MADRID 14-12 FOLLOW UP

API#: 05-071-06226

INSP. #: 695101811



Colorado Oil & Gas Conservation Commission  
37.18196, -104.73873, 2190.0m, 180°  
2019/11/21 12:16:28

**PHOTO 1: LOCATION**



Colorado Oil & Gas Conservation Commission  
37.18149, -104.73904, 2175.0m, 283°  
2019/11/21 12:18:40

**PHOTO 2: WELL SIGN**

## Inspection Photos

Location Name: MADRID 14-12 FOLLOW UP

API#: 05-071-06226

INSP. #: 695101811



**PHOTO 3: UNUSED EQUIPMENT (GREEN UPRIGHT TANK).**

**REMOVE UNUSED EQUIPMENT PER RULE 603.f. THIS IS THE  
2<sup>ND</sup> NOTICE OF UNUSED EQUIPMENT IF CA IS NOT  
ADDRESSED PRIOR TO NEXT INSPECTION ENFORCEMENT  
WILL BE CONSIDERED. CA DATE 01-21-20**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources