

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Aerial view of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #1 – View of impacted fluids on the west side of the tank battery.



Photo #2 - View of impacted fluids on the west side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #3 - View of impacted fluids on the west side of the tank battery.



Photo #4 – View of the residual staining ring approximately three to four inches above the gravel in the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #5 – View of impacted gravel on the east side of the tank battery.



Photo #6 – View of the replacement 300 BBL Condensate and Produced Water AST.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #7 – View of the impacted gravel in the eastern section of the tank battery.



Photo #8 - View of the impacted gravel in the eastern section of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #9 - View of the impacted gravel in the eastern section of the tank battery.



Photo #10 - View of the PetroFlag sample point (Red Circle).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #11 – View of PetroFlag sample point (Red circle) and the impacted fluids with a detectable odor and sheen located on the east side of the tank battery underneath the gravel / on top of the liner.



Photo #12 – View of the PetroFlag results.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #13 - View of the impacted gravel in the eastern section of the tank battery.



Photo #14 - View of the impacted gravel in the eastern section of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #15 - View of the impacted gravel in the eastern section of the tank battery.



Photo #16 – View of fluids with no detectable odor or sheen located on the west side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #17 – View of the western side of the tank battery.



Photo #18 – View of the eastern side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #19 – View of COGCC staff inspecting the separator housing.



Photo #20 – 500 Gallon Methanol Tank labeled Laramie Energy.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #21 – View of the hot, soapy water rinse on the east side of the tank battery.



Photo #22 - View of the hot, soapy water rinse on the east side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #23 - View of the hot, soapy water rinse on the north side of the tank battery.



Photo #24 - View of the hot, soapy water rinse on the south side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #25 - View of the hot, soapy water rinse on the west side of the tank battery.



Photo #26 - View of the hot, soapy water rinse on the west side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HOOKER 30-02-693

Location ID: 383273 & Spill/Release ID: 468820

Inspection Date: October 21,23,24,30 and November 1, 2019



Photo #27 – View of the hot, soapy fluids on the west side of the tank battery.



Photo #28 - View of the hot, soapy water rinse on the west side of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources