

Inspection Photos

Loc#311622

Operator: Caerus

Inspection Number: 692401593

Inspection Date: 11/15/19





Photo#1:
Overview of Location to Northeast.

November 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Savage Loc#311622



Photo#2:
Vegetation is successful and uniform in Interim areas



Photo#3:
Vegetation is successful and uniform in Interim areas

November 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Savage Loc#311622



Photo#2:
Desiccated Thistle.



Photo#3:
Subsidence, worm hole on Northwest edge of Pad.

November 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Savage Loc#311622