

## WELL SITE INSPECTION FORM



00219449

WELL NAME COLORADO SOUTHERN 35-1  
OPERATOR COLORADO SOUTHERN  
LOCATION 660' E, 1980' N, 35-6N-67W  
FIELD SOUTH LA Poudre

API NUMBER 05-123-14525  
PERMIT NUMBER 89-186  
COUNTY WELD  
INSPECTOR P. VanSickle

## AL/PA/DA INSPECTION RESULTS:

PASS(Y) \_\_\_\_\_ FAIL(N) \_\_\_\_\_ DATE \_\_\_\_\_

## WELL STATUS:

FN \_\_\_\_\_ FD ☒ WO \_\_\_\_\_

DATE OF INSPECTION (BEFORE) DURING DRILLING 1-4-90

CASING SIZE 7.52 DEPTH SET 730' CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG VIRGINIA DRILLING BOP'S NONE CONTACT NONE

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_  
DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_  
TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_  
SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls  
EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_  
METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

## AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_ DATE PERMIT EXPIRED: \_\_\_\_\_  
HOLE PLUGGED: YES \_\_\_\_\_ NO \_\_\_\_\_ PITS BACKFILLED: YES \_\_\_\_\_ NO \_\_\_\_\_  
MATERIAL BURIED: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ SITE CLEAN: YES \_\_\_\_\_ NO \_\_\_\_\_  
BOND RELEASE OK: YES \_\_\_\_\_ NO \_\_\_\_\_ FED \_\_\_\_\_ HOLE MARKER: YES \_\_\_\_\_ NO \_\_\_\_\_

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS No activity on location - Spudder in hole. Appears that there is about 30' of 4 1/2" casing in the ground.