

**Inspection Photos**  
**Location Name: Ross-Government-USA 43-7**  
**Location ID: 312938**



**Photo 1. Overview of location taken facing east.**



**Photo 2. Landfarm area from previous report, no oily soil observed during this inspection.**



**Inspection Photos**  
**Location Name: Ross-Government-USA 43-7**  
**Location ID: 312938**



**Photo 3. Unused equipment becoming debris, dried annual weeds.**



**Photo 4. Pit.**

