

Buckhorn Draw Unit 6607B G11 299

API: 05-103-11601

Inspection: 679706156



39.89352, -108.46949, 6933.2ft, 35°

11/22/2019 01:11:00 PM

Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Buckhorn Draw Unit 6607B G11 299

API: 05-103-11601

Inspection: 679706156



Photo 2. Separator & tanks.



Buckhorn Draw Unit 6607B G11 299

API: 05-103-11601

Inspection: 679706156



39.89383, -108.46894, 6920.2ft, 118°

11/22/2019 01:13:12 PM

Photo 3. Tanks.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Buckhorn Draw Unit 6607B G11 299

API: 05-103-11601

Inspection: 679706156



Photo 4. Stained gravel?



Photo 5. Stained gravel?