

RGU 41-8-298
API: 05-103-10706
Inspection: 679706268



39.89558, -108.40824, 6687.7ft, 263°
11/22/2019 02:48:19 PM

Photo 1. Location.

RGU 41-8-298
API: 05-103-10706
Inspection: 679706268



Photo 2. Separator.



RGU 41-8-298
API: 05-103-10706
Inspection: 679706268



Photo 3. Tanks.



RGU 41-8-298
API: 05-103-10706
Inspection: 679706268




Photo 4 Tanks label.