

West Dragon Trail 4016

API: 05-103-09612

Inspection: 679706277



Photo 1. Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

West Dragon Trail 4016

API: 05-103-09612

Inspection: 679706277

Gas leak



39.84353, -108.88545, 6953.5ft, 348°

11/25/2019 08:36:34 AM

Photo 2. Well head plunger.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources