

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/19/2019

Document Number:

698100095

**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 335875      Arauza, Steven      2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER      State: CO      Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3      Number of Comments

1      Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Heil, John		john.heil@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292470	WELL	PR	05/01/2018	SI	045-14727	596-31A 12	EI
293641	WELL	PR	07/01/2018	SI	045-15077	596-31A 28	EI
293642	WELL	PR	06/01/2018	SI	045-15078	596-31A 27	EI
293643	WELL	PR	06/01/2018	SI	045-15079	596-31A 26	EI
293644	WELL	PR	07/01/2018	SI	045-15080	596-31A 25	EI
293645	WELL	PR	06/01/2018	SI	045-15081	596-31A 24	EI
293646	WELL	PR	06/01/2018	SI	045-15082	596-31A 23	EI
293647	WELL	PR	08/01/2018	GW	045-15083	596-30C 28	EI
293648	WELL	PR	10/29/2010	GW	045-15084	596-31A 21	EI
293650	WELL	PR	08/01/2018	SI	045-15086	596-31A 17	EI
293651	WELL	PR	06/01/2018	SI	045-15087	596-31A 16	EI
293652	WELL	PR	07/01/2018	SI	045-15088	596-31A 15	EI
293653	WELL	PR	06/01/2018	SI	045-15089	596-31A 14	EI
293654	WELL	PR	06/01/2018	SI	045-15090	596-31A 13	EI
293655	WELL	PR	05/01/2018	OW	045-15091	596-31A 11	EI

**General Comment:**

Inspector Name: Arauza, Steven

COGCC Environmental Inspection. Follow-up to 8/30/2019 Field Inspection Report (FIR) #698100068. Weather conditions during inspection were sunny with a temperature of 49 degrees Fahrenheit.

Operator has updated emergency contact numbers on all well signs. The phone number was tested on 11/15/2019 and rings to a live answer. See photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	On inspection date, gas concentration within the separator shed for 31A #25, #26, #27, and #28 wells was sufficient to trigger LEL alarm (20% LEL) on inspector's four-gas meter. Operator was notified of gas leak via phone on 11/15/2019		
Corrective Action:	Immediately fix or isolate leak. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (separator)		Date: 12/04/2019

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: <u>292470</u>	Type: <u>WELL</u>	API Number: <u>045-14727</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293641</u>	Type: <u>WELL</u>	API Number: <u>045-15077</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293642</u>	Type: <u>WELL</u>	API Number: <u>045-15078</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293643</u>	Type: <u>WELL</u>	API Number: <u>045-15079</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293644</u>	Type: <u>WELL</u>	API Number: <u>045-15080</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293645</u>	Type: <u>WELL</u>	API Number: <u>045-15081</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293646</u>	Type: <u>WELL</u>	API Number: <u>045-15082</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293647</u>	Type: <u>WELL</u>	API Number: <u>045-15083</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293648</u>	Type: <u>WELL</u>	API Number: <u>045-15084</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293650</u>	Type: <u>WELL</u>	API Number: <u>045-15086</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293651</u>	Type: <u>WELL</u>	API Number: <u>045-15087</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293652</u>	Type: <u>WELL</u>	API Number: <u>045-15088</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293653</u>	Type: <u>WELL</u>	API Number: <u>045-15089</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293654</u>	Type: <u>WELL</u>	API Number: <u>045-15090</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>293655</u>	Type: <u>WELL</u>	API Number: <u>045-15091</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402243603	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992537">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992537</a>
698100100	20191114 field photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992534">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992534</a>