

Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: November 12, 2019




Photo #1 – Location sign.



Photo #2 – View of the 80 bbls produced water tank with an earthen berm.



Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: November 12, 2019



Photo #3 – View of the 2-inch flowline penetrating the south side of the earthen berm (Red circle).



Photo #4 – View of staining on the containment of the plastic ASTs.



Inspection Photos
Location Name: YOUNBERG 32-12
Location ID: 324061
Inspection Date: November 12, 2019



Photo #5 - View of staining on the containment of the plastic ASTs and the soil beneath the containment. Unused equipment is also present in the photo.



Photo #6 – View of stained soil located south of the wellheads.

