

Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 1 –



Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 2 – Tank battery



Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 3 – Tank battery



Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 4 – Jones #1 well sign adjacent to stacked pipe and junk and trash

Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 5 – Former oil skim pit area

Location Name: Central Operating – State A – Rem #9144  
Inspection Date: 11/25/2019



Photo # 6 – Produced water pit view north

