

**Inspection Photos**  
**Location Name: Castor Federal LG 17-62HN**  
**Location ID: 425512**




**Photo 1 – Tank Battery**



**Photo 2 – Stained Soil at Wellhead, Unused Wellhead parts,  
Unmarked 2" Riser**

**Inspection Photos**  
**Location Name: Castor Federal LG 17-62HN**  
**Location ID: 425512**



**Photo 3 – Unused Wellhead parts**