

Construction and Stormwater Inspection

November 25, 2019

Operator: VERDAD RESOURCES LLC- #10651

Location ID: 467102

Inspection Document #: 697500870

Weld County, CO

SESE Section 20 T9N R58W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 1. Photo taken from the southwestern perimeter of location, facing East. Photo illustrates a ditch and berm BMP installed around the entire perimeter of location. Operator also has another ditch BMP along portions of the western, northern and eastern well pad. Also, photo illustrates one of two soil stockpiles that have been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 2. Photo taken from the southwestern perimeter of location, facing North. Photo illustrates a ditch and berm BMP installed around the entire perimeter of location. Also, photo illustrates the second soil stockpile that has been temporarily stabilized with equipment tracking.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 3. Photo taken from the western perimeter of location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 4. Photo taken from the northwestern perimeter of location, facing East. Photo illustrates a ditch and berm BMP installed around the entire perimeter of location.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 5. Photo taken from the northeastern perimeter of location, facing West. Photo illustrates the ditch BMP around the entire well pad perimeter.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



11.25.2019 14:42

Photo 6. Photo taken from the northeastern perimeter of location, facing South. See comments under Photo 5.

Inspection Photos
Location Name: Bringelson Fed /2021 & 2029
Location ID: 467102



Photo 7. Photo taken from the southeastern perimeter of location, facing West. See comments under Photo 1.