



99999999

## WELL SITE INSPECTION FORM

WELL NAME Mallon State 17-5  
OPERATOR Mallon  
LOCATION SENW 17, 6N, 86W  
FIELD Tow Creek

API NUMBER 05 (107 - 8155)  
PERMIT NUMBER \_\_\_\_\_  
COUNTY Rowt  
INSPECTOR Kathy Buehl

AL/PA/DA INSPECTION RESULTS:

PASS(Y) Y FAIL(N) \_\_\_\_\_ DATE 10-4-89

WELL STATUS:

FN \_\_\_\_\_ FD \_\_\_\_\_ WO \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING DRILLING \_\_\_\_\_

CASING SIZE \_\_\_\_\_ DEPTH SET \_\_\_\_\_ CMT VOL \_\_\_\_\_ WOC \_\_\_\_\_  
CONSISTENT WITH APD CASING PROGRAM? \_\_\_\_\_ RETURNS \_\_\_\_\_  
RIG \_\_\_\_\_ BOP'S \_\_\_\_\_ CONTACT \_\_\_\_\_

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION \_\_\_\_\_

PIPE SET? \_\_\_\_\_ COMPLETION RIG/ACTIVITY \_\_\_\_\_

DRILLING PITS: CLOSED \_\_\_\_\_ OPEN \_\_\_\_\_ WELLHEAD SYSTEM INSTALLED \_\_\_\_\_

TANK ID: YES \_\_\_\_\_ NO \_\_\_\_\_ NA \_\_\_\_\_ WELL SIGN: YES \_\_\_\_\_ NO \_\_\_\_\_

SKIM PIT: \_\_\_\_\_ gal TANKS: ( ) \_\_\_\_\_ bbls

EQUIPMENT \_\_\_\_\_

BRADENHEAD PRESSURE \_\_\_\_\_ FLUID: NO \_\_\_\_\_ YES \_\_\_\_\_ TYPE \_\_\_\_\_

METER RUN: YES \_\_\_\_\_ NO \_\_\_\_\_ WELL STATUS: PR \_\_\_\_\_ TA \_\_\_\_\_ SI \_\_\_\_\_ WELL CAT 3- \_\_\_\_\_

AL/PA/DA INSPECTION

DATE PLUGGED: \_\_\_\_\_

DATE PERMIT EXPIRED: \_\_\_\_\_

HOLE PLUGGED: YES ☒ NO \_\_\_\_\_PITS BACKFILLED: YES ☒ NO \_\_\_\_\_MATERIAL BURIED: YES ☒ NO \_\_\_\_\_ NA \_\_\_\_\_SITE CLEAN: YES ☒ NO \_\_\_\_\_BOND RELEASE OK: YES ☒ NO \_\_\_\_\_ FED \_\_\_\_\_HOLE MARKER: YES \_\_\_\_\_ NO ☒

DATE OF SAFETY/STATUS INSPECTION \_\_\_\_\_

COMMENTS Back hoe just finishing recontouring hillside.

00197532