

**Inspection Photos**  
**Location Name: Seventy Holes 24-5 PAD**  
**Location ID: 429065**



**Photo 1 – Tank Battery**




**Photo 2 – Wellheads**

**Inspection Photos**  
**Location Name: Seventy Holes 24-5 PAD**  
**Location ID: 429065**



**Photo 3 – Debris inside Secondary Containment and Wildlife Netting is in disrepair.**



**Photo 4 – Stained Soil at Compressor**