

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/26/2019

Submitted Date:

11/26/2019

Document Number:

697000252

FIELD INSPECTION FORM

Loc ID 432360 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10634
Name of Operator: P O & G OPERATING LLC
Address: 5847 SAN FELIPE SUITE 3200
City: HOUSTON State: TX Zip: 77057

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hudson, Glen	713-589-8186	glenn_hudson@pogresources.com	Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432361	WELL	PR	05/17/2018	OW	017-07748	Chesnee 2	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease signs by tanks		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	Electric panel and cathodic rectifier		
Corrective Action:		Date:	
Type: FWKO	# 1		
Comment:	FWKO on west side of tanks		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Caprock 320		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	FIBERGLASS AST		38.854460,-102.369930
Comment: 2-Water tanks on south side of oil tanks					
Corrective Action:					Date:

Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shared berms					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	FIBERGLASS AST		38.854460,-102.369930
Comment: Central tank battery for Evans 2 and Chesnee 2					
Corrective Action:					Date:

Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:					
Yes/No	YES				
Comment: 2" casing vent					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 432361 Type: WELL API Number: 017-07748 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Chesnee 2 and Evans 2\) 550' E @ 38.854460/-102.369930](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT