

Buckhorn Draw Unit 6606A F01 199, 1-2-199

API: 05-103-11602, 11759

Inspection: 679706351



Photo 1. Location.



Buckhorn Draw Unit 6606A F01 199, 1-2-199

API: 05-103-11602, 11759

Inspection: 679706351



Photo 2. Separator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Buckhorn Draw Unit 6606A F01 199, 1-2-199

API: 05-103-11602, 11759

Inspection: 679706351



40.00214, -108.45757, 6772.4ft, 325°
11/27/2019 11:18:18 AM

Photo 3. Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Buckhorn Draw Unit 6606A F01 199, 1-2-199
API: 05-103-11602, 11759
Inspection: 679706351



Photo 4. Tank label.



Photo 5. Container with no secondary containment.

Buckhorn Draw Unit 6606A F01 199, 1-2-199
API: 05-103-11602, 11759
Inspection: 679706351



Photo 6. Container without label.