

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/27/2019

Submitted Date:

11/29/2019

Document Number:

679706351**FIELD INSPECTION FORM**Loc ID 418199 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413144	WELL	SI	08/01/2019	GW	103-11602	BUCKHORN DRAW UNIT 6606A F01 199	SI
418183	WELL	SI	08/01/2019	GW	103-11759	BDU 1-2-199	SI
439946	WELL	AL	02/21/2018	LO	103-12168	BDU 1-4-199	AL
439948	WELL	AL	02/21/2018	LO	103-12169	BDU 1-8-199	AL
440773	WELL	AL	02/21/2018	LO	103-12208	BDU 1-3-199	AL
440774	WELL	AL	02/21/2018	LO	103-12209	BDU 1-1B-199	AL
440775	WELL	AL	02/21/2018	LO	103-12210	BDU 1-1-199	AL
441011	WELL	AL	02/21/2018	LO	103-12211	BDU 1-7-199	AL

**General Comment:**[COGCC Inspection Report Summary.](#)

On 11-27-2019 at approximately 11:15, inspector Rick Moran, conducted a routine inspection at Laramie Energy Buckhor Draw Unit 6606A F01 199 and 1-2-199 in Rio Blanco county.

The following compliance issues were observed:

- 1) Two tanks without the '400 bbl capacity' label. Photo 4. Complete by 1-29-2020.
- 2) Container without secondary containment. Photo 5. Complete by 1-29-2020.
- 3) Metal container without label. Photo 6. Complete by 1-29-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706351.

**Location**Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:	Metal container without a label. Located inside tank battery secondary containment.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/29/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Two tanks without the '400 bbl capacity' label.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/29/2020

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Container of methanol, MC MX 6-3937, and an unknown container all with secondary containment. A container of diethanolamine without secondary containment.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		40.002250,-108.457550
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	STEEL AST		40.002250,-108.457550
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 413144 Type: WELL API Number: 103-11602 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last recorded production July 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418183 Type: WELL API Number: 103-11759 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last recorded production July 2019.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 439946 Type: WELL API Number: 103-12168 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Permit abandon 2-21-2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 439948 Type: WELL API Number: 103-12169 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Permit abandon 2-21-2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440773 Type: WELL API Number: 103-12208 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Permit abandon 2-21-2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440774 Type: WELL API Number: 103-12209 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Permit abandon 2-21-2018.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 440775 Type: WELL API Number: 103-12210 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Permit abandon 2-21-2018.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 441011 Type: WELL API Number: 103-12211 Status: AL Insp. Status: AL

**Idle Well**

Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Permit abandon 2-21-2018.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	

Comment: [Container of diethanolamine without secondary containment.](#)

Corrective Action: [Repair or install berms or other secondary containment devices per Rule 605.a.\(4\).](#)

Date: 01/29/2020

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706352	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5000609</a>