



99999999

WELL CATEGORY : 3 -

API (075 06652)

WELL SITE INSPECTION FORM

LOCATION NE NENW 6 - 9N - 52W
OPERATOR Quest Oil Co.
WELL NAME Richerson #1

FIELD Padroni West
COUNTY Logan
PERMIT #

DATE OF INSPECTION DURING DRILLING:

RIG SURFACE CASING: DEPTH:
BOP'S RETURNS: WOC:
CONTACT CMT VOL:
ADEQUATE AQUIFER PROTECTION?
COMMENTS

DATE OF INSPECTION AFTER COMPLETION:

FRACED: YES NO PRODUCTION STRING:
WATER DISPOSAL: PITS , INJECTED , COMMERCIAL , UNKNOWN , N.A.
PITS: PERMIT Y N , SKIM TANK Y N , DIMENSIONS GALLONS
LEASE SIGN: YES NO TANK ID: YES NO NA FENCED: YES NO
SURFACE EQUIPMENT:
COMMENTS:

DATE OF P&A INSPECTION 6/24/87

PITS BACKFILLED: YES ✓ NO SURFACE RECLAIMED: YES ✓ NO
HOLE MARKER: YES NO ✓ SITE CLEAN: YES ✓ NO
BOND RELEASE OK: YES ✓ NO LANDOWNER RELEASE: YES NO
COMMENTS: 5/1/86 plugged well, dirt work to finish (6/18/86, 7/30/86 - No change)
6/24/87 Final P&A inspection OK.

DATE OF SAFETY INSPECTION

COMMENTS:

INSPECTOR SPAPI No. 05-075-06652P&A Inspected: Yes ✓ No 

00238301