

Inspection Photos
Location Name: Pronghorn 14-11-4HNB
Location ID: 433146



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Pronghorn 14-11-4HNB
Location ID: 433146



Photo 3 – Unmarked 3” Riser at Wellhead



Photo 4 – Unmarked Riser on South side of location

Inspection Photos
Location Name: Pronghorn 14-11-4HNB
Location ID: 433146



Photo 5 – Unmarked 3” Riser east of Pipe Rack