



99999999

WELL SITE INSPECTION FORM

Well Name V. O. MORTON #3 API Number 05 - 107 - 5069
Operator MIRACLE FIFER DRWG. Permit #
Location NWNE 19-6N-86W County ROUTT
Field TOW CR Inspector R. Van Sickle
AL/PA/DA Inspection Results: Well Status:
Pass (Y) ☒ Fail (N) ☐ Date 8-3-90 FN ☐ FD ☐ WO ☐ PR ☐ SI ☐

Date of Inspection Before/During Drilling

Surf. Csg. Size Setting Depth Cmt. Vol. WOC time
Consistent with APD casing Program? YES ☐ NO ☐ Returns
Rig BOP'S Contact

Date of Inspection Before/During/After Completion

Prod. Csg. Set? Completion Rig/Activity
Drilling Pits: Closed ☐ Open ☐ Wellhead Installed: Sign: Yes ☐ No ☐
Tank ID: Yes ☐ No ☐ N/A ☐ Skim Tank/Pit: Prod. Tanks: () BBLS
Equipment Meter Run: Yes ☐ No ☐
Bradenhead Press: Fluid: No ☐ Yes ☐ Type Well Cat.

AL/PA/DA Inspection

Date Plugged: 7-20-60 Date Permit Expired:
Hole Plugged: Yes ☒ No ☐ Pits Backfilled: Yes ☒ No ☐
Material Buried: Yes ☒ No ☐ N/A ☐ Site Clean: Yes ☒ No ☐
Bond Release OK: Yes ☒ No ☐ Fed ☐ Hole Marker: Yes ☒ No ☐

Date of Safety/Status Inspection

Comments:



00212988

Violations: Yes ☐ No ☒ Notice Sent: Yes ☐ No ☐ Date Sent: