

Inspection Photos

API: 05-073-06318

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 11/25/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019

Inspection Photos



Photo 1. Facing south at the location which is west of active tank battery site. Soils are compacted and vegetation is not establishing. Corrective action not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019

Inspection Photos



Photo 2. Facing east at the location which is west of active tank battery site. Soils are compacted and vegetation is not establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-073-06318 | Date: 11/25/2019