

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 1 Denver, CO 80203 (303)894-2100	
API No. 05- 075 - 08870		LEASE NAME: Davis	
LOCATION: NENE 29-9N-53		OPERATOR: Donnelly	
DATE: 4-8-96		INSPECTOR: Birtley	
Insp. Type: SP	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/> Viol: Y <input type="radio"/> N <input checked="" type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	wheat field	
Miscellaneous	KN - gas line 2" riser 6' high 2 valves.	

CORRECTIVE ACTION REQUIRED: Notified Donnelly to finish cleanup of battery site. Riser is live gas line - unmarked.	
Date Corrective Action Required By: 4-30-96	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

APR 18 1996