

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Colorado Oil and Gas Conservation Commission
• 40.38438, -104.76482, 1448.2m, 324°
Dec 4, 2019 11:56:35

Photo 3: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.38438, -104.76484, 1447.4m, 155°
Dec 4, 2019 11:56:44

Photo 4: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Photo 5: Wellhead Sign



Photo 6: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Colorado Oil and Gas Conservation Commission
40.38439, -104.76493, 1446.5m, 219°
Dec 4, 2019 11:57:13

Photo 7: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.38438, -104.76495, 1445.7m, 124°
Dec 4, 2019 11:57:22

Photo 8: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Photo 9: Wellhead Sign



Photo 10: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Colorado Oil and Gas Conservation Commission
•40.38437, -104.76505, 1446.4m, 233°
Dec 4, 2019 11:57:52

Photo 11: Wellhead Sign



Colorado Oil and Gas Conservation Commission
40.38438, -104.76507, 1446.8m, 132°
Dec 4, 2019 11:57:58

Photo 12: Wellhead

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Photo 13: Location



Photo 14: Tank Battery

Inspection Photos
Location Name: T-Bone Ranch Directional 1
Location ID: 423341



Photo 15: BBLs/contents faded




Photo 16: BBLs/contents faded