

ADO OIL & GAS CONSERVATION FIELD INSPECTION REPORT



99999999

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 075 - 6360

LEASE NAME: mt. Hope 41

LOCATION: SE NW 30-9N-53

OPERATOR: Monahan

DATE: 12-2-97

INSPECTOR: **ED BINKLEY 970/842-4465**

Insp. Type: ID

Insp. Status: TA

PA: Y N

Pass/Fail: P ☒ F

Viol: ☒ Y N

NOV: Y ☒ N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	<u>Monahan plans to plug</u>	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	<u>this well within 6 months</u>	
Tank Battery Equipment (Rule 603.b.3, 604)	<u>per Sam Rowland -</u>	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	<u>9/1/97</u>	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

