

Inspection Photos

API#081-06217

Operator: Jetta Operating

Inspection Number: 692401623

Inspection Date: 11/8/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to North. Insert of road that runs through site and North to river.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Jetta OP PA Craig API#081-06217



Photo#2:

Overview of Location to South. Insert of road that runs through site and South to Golf Course road.

November 7, 2019



Photo#3:
Cable / Debris on site.



Photo#4:
Cable / Debris on site..

November 7, 2019



Photo#5:
Anchor installed on site.



Photo#6:
Anchor installed on site.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Jetta OP PA Craig API#081-06217