

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402255214

Date Received:

12/05/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

4 of 7 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Jessica Dooling

Phone

970-675-4122

Email

jessica\_dooling@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700068

Inspection Date: 11/13/2019

FIR Submit Date: 12/04/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqtr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.963402 Longitude: -108.266120

FACILITY - API Number: 05-103- -00 Facility ID: 469300

Facility Name: SPILL/RELEASE POINT Number: 441601

Qtrqtr: NWSE Sec: 15 Twp: 1S Range: 97W Meridian: 6

Latitude: 39.963402 Longitude: -108.266120

CORRECTIVE ACTIONS:

**1** CA# 135092

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 12/19/2019

Response: CA COMPLETED

Date of Completion: 12/05/2019

Operator Comment: RNPU 197-15A1, Location ID 441601, discolored gravel within secondary containment is result os snow melt. In a conversation on 12/5/2019 between Natalie Steiner (XTO) and John Heil, John indicated he agreed and this should be noted in the FIRR.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 135093

Corrective Action: Comply with Rule 603.f. For unused, unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.

Date: 12/05/2019

Response: CA COMPLETED

Date of Completion: 12/05/2019

Operator Comment: 12/5/2019 LOTO has been applied to flowline riser, see attached photo

COGCC Decision:

COGCC  
Representative:

3 CA# 135094

Corrective Action: Install or remove sign to comply with Rule 210.a.

Date: 12/07/2019

Response: CA COMPLETED

Date of Completion: 12/05/2019

Operator Comment: Sign removed 12/5/2019, please see attached photo

COGCC Decision:

COGCC  
Representative:

7 CA# 135098

Corrective Action: Report release of E&P waste or produced fluids. 24 hours to remove free fluids and 72 hours for Initial Form 19 Report.

Date: 12/07/2019

Response: CA COMPLETED

Date of Completion: 12/05/2019

Operator Comment: Love Ranch 1 Tank Battery, impacted soil was result of 11/13/2019 produced water release that was below COGCC 900 Series reportable quantity. In a conversation between Natalie Steiner (XTO) and John Heil on 2/5/2019 situation was discussed. John indicated that no Form 19 was required and note should be made in FIRR.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please contact me with any comments or questions. Additional FIRR will be submitted when remaining CAs are completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jessica Dooling

Signed:

Title: Regulatory Coordinator

Date: 12/5/2019 1:27:54 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402255266	20191205 LOTO installed
402255273	20191205 Sign Removed

Total Attach: 2 Files