

Inspection Photos

Location Name: TRUE BLUE 42-3 FOLLOW UP

API#: 05-071-09432

INSP. #: 695101864



PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: TRUE BLUE 42-3 FOLLOW UP

API#: 05-071-09432

INSP. #: 695101864



PHOTO 3: LINER HAS DETERIORATED AND HAS SEVERAL HOLES IN IT. REMOVE (IF NOT REQUIRED) OR MAINTAIN LINER IN ACCORDANCE WITH RULE 904. CA DATE 02-05-20

PHOTO 4: ANOTHER IMAGE OF CONDITION OF PIT LINER

Inspection Photos

Location Name: TRUE BLUE 42-3 FOLLOW UP

API#: 05-071-09432

INSP. #: 695101864



PHOTO 5: OILY IMPACTED SOIL NEAR ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-05-20

PHOTO 6: ANOTHER IMAGE OF OILY IMPACTED SOIL NEAR ENGINE SKID. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 01-05-20

Inspection Photos

Location Name: TRUE BLUE 42-3 FOLLOW UP

API#: 05-071-09432

INSP. #: 695101864



Colorado Oil & Gas Conservation Commission
37.20215, -104.76095, 2236.0m, 12°
2019/12/05 13:22:47



Colorado Oil & Gas Conservation Commission
37.20212, -104.76088, 2241.0m, 233°
2019/12/05 13:23:25

PHOTO 7: UNUSED EQUIPMENT STORED ON LOCATION (ENGINE SKID AND SOUND WALLS). REMOVE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE 01-05-20

PHOTO 8: UNUSED EQUIPMENT STORED ON LOCATION (WELLHEAD EQUIPMENT, 2" PIPE AND PC PUMP W/SUB). REMOVE UNUSED EQUIPMENT IN ACCORDANCE WITH RULE 603.f. CA DATE 01-05-20

Inspection Photos

Location Name: TRUE BLUE 42-3 FOLLOW UP

API#: 05-071-09432

INSP. #: 695101864



PHOTO 9: GRASS/WEEDS AROUND WELLHEAD.
CUT/MAINTAIN GRASS/WEEDS IN ACCORDANCE WITH RULE
603.f. CA DATE 01-05-20

PHOTO 10: : GRASS/WEEDS AROUND METERRUN.
CUT/MAINTAIN GRASS/WEEDS IN ACCORDANCE WITH RULE
603.f. CA DATE 01-05-20