

Inspection Photos

API#081-06441


Operator: HRM Resources

Inspection Number: 692401613

Inspection Date: 11/7/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overviews of Location to North & South at Well GPS Position.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA API#081-06441



J-W MEASUREMENT COMPANY
A subsidiary of J.W. Operating Company
1-800-333-4860

Meter Record

Add _____ Gp _____
Station No. 0867
Station Name CHL-1-150 System CHL-1-150
Producer _____ Fed. ID # 00000000
Sec. 33 Twp. 10N Rng. 7E County Elbert
Dist. Rng. 10C Stat. Rng. 50C
Temp. Rng. 15C Absolute 11.97
Meter Serial # 300E-110724 Tube Size 2.567
Meter I.D. _____ Core O.D. _____

Orifice Plate			Meter Seal	
Date	Size	Coefficient	Date	Seal
11-29-08	2.575	1.872	11-29-08	CHL-1
6-29-08	2.575	1.872	6-29-08	CHL-1
6-29-08	2.575	1.872	6-29-08	CHL-1
7-17-07	2.575	1.872	7-17-07	CHL-1
11-6-07	2.575	1.872	11-6-07	CHL-1
11-6-07	2.575	1.872	11-6-07	CHL-1



Photo#2:
Shed housing equipment.


Photo#3:
View of equipment Inside shed; last date
on meter card is 9-10-08

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA API#081-06441



Photo#4:
Unknown Risers on site.



Photo#5:
Unknown Risers on site.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA API#081-06441



Photo#6:
Overview of Location to East.

November 7, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: HRM Res PA API#081-06441