

**Inspection Photos**  
**Operator: Williford Resources**  
**Location/API #: 067-06623**  
**Date: 11-19-2019**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with sagebrush, snakeweed, and sand dropseed.



Photo 3. View of reference area, comprised of sagebrush shrubland, with snakeweed and sand dropseed.