

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402258396

Date Received:

12/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687905348

Inspection Date: 07/30/2019

FIR Submit Date: 07/30/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306921

Location Name: WARREN DAVIS GAS UNIT Number: 13NWSW County: LA PLATA
C-N33N9W

Qtrqtr: NWS Sec: 13 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.101333 Longitude: -107.783098

FACILITY - API Number: 05-067- -00 Facility ID: 277999

Facility Name: WARREN DAVIS C Number: 2

Qtrqtr: NWS Sec: 13 Twp: 33N Range: 9W Meridian: N
W

Latitude: 37.101333 Longitude: -107.783098

CORRECTIVE ACTIONS:

1 CA# 128681

Corrective Action: Remove unused equipment per Rule 603.f.

Date: 10/30/2019

Response: CA COMPLETED

Date of Completion: 09/12/2019

All operator debris removed from location see attached

--

Corrective action addressed see attached.

Print Name: Sahra Rashe Signed:

Signed:

Date: 12/9/2019 3:33:39 PM

*** website: <http://www>