



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Patrick Bateman (p.bateman@kosinm.com)
Submission Date:	Sep 19, 2019 10:31:22 AM MDT
Server Receive Date:	Sep 19, 2019 10:31:47 AM MDT
Reference Number:	20190919-18117782829
Location:	3601 N 1st St, Bloomfield, NM 87413, USA Sep 19, 2019 10:31:20 AM MDT [ <a href="#">View Map</a> ]

## Information

Name	p.bateman@kosinm.com
Date	Sep 12, 2019
Well Name	DAVIS, WARREN GAS UNIT C 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed



Completed work description of corrective action 2

Completed work description of corrective action 3

Picture from where the sound walls had been stored

Anchor markers

.

Completed work description of corrective action 4

Summary of all work completed

.  
Removed sound walls from location. Cleaned all trash and debris and checked all signs. Marked rig anchors. Checked all other inspection items and nothing noted.