



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Sep 24, 2019 1:09:23 PM MDT
Server Receive Date: Sep 24, 2019 1:11:16 PM MDT
Reference Number: 20190924-18118297218
Location: 557 Airpark Dr, Durango, CO 81303, USA
Sep 24, 2019 1:09:07 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Sep 18, 2019
Well Name PAYNE, EVELYN GAS UNIT F 2
API Number 50670888100
Select State Colorado
Work type COGCC Inspection AR
Action Complete Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated noxious weeds in reclamation area

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

treated noxious weeds in reclamation area



Completed work description of corrective action 4
 Summary of all work completed

treated noxious weeds in reclamation area
 treated noxious weeds in reclamation area