

Inspection Photos
Location Name: Windsor 35-5
Location ID: 310283




Photo 1: Tank Battery Sign



Photo 2: Tank Battery; inadequate berm/tanks not anchored



Inspection Photos
Location Name: Windsor 35-5
Location ID: 310283



Photo 3: H2O tank not anchored



Photo 4: Separator not anchored

