

Inspection Photos

Location Name: ROUSE USX A-66N64W /5SWNW

Location #: 302562



Photo #1

Rouse USX A 05-05 (05-123-29403) Wellsite

Shut-In | SI

Invalid Emergency number posted



Photo #2

Rouse USX A 05-03, 04, 05, 06, 19 Battery site

Inactive | Shut-down