

Inspection Photos

Location Name: ROUSE-USX A-66N64W /5NWNW

Location #: 306456



Photo #1

Rouse-USX A 05-19 (05-123-24697) Wellsite

Shut-In | SI

Invalid Emergency number posted



Photo #2

Rouse USX A 05-03, 04, 05, 06, 19 Battery site

Inactive | Shut-down